


SEA FROST ELECTRONIC THERMOSTAT AND THERMOMETER

DRILL (4) HOLES 3/32" FOR #6 SCREWS.



- (1) Control Panel Head
- (2) Sensor Probes (1-with red band, 1-without red band)
- (1) Cat 5 cable with RJ 45 Connector

INSTALLATION KIT

- (4) #6 x 1/2" flat head screws for mounting panel
- (6) #6 x 1/2" pan head screws
- (5) 3/16" nylon clamps
- (8) Adhesive mounting tabs
- (10) 4" tie wraps
- (1) Stainless steel bulb clip
- (1) Fuse